ltem Qty **Part Number** Description Qty -241 -241B Х D212-664-241 **CROSSTUBE ASSEMBLY (205/212 HIGH AFT)** 2 X D212-664-241B **CROSSTUBE ASSEMBLY (214 HIGH AFT)** D6006-129 CROSSTUBE 4 2 D2940-1 SUPPORT D3595-063-530 **RUBBER CUSHION** 4 D5018-1 **SUPPORT** 6 2 MS21920-28 CLAMP (OR MS21920-30) 4 4 A/R A/R PROSEAL 890 B-2 SEALANT, AMS-S-8802 CLASS B-2 8



/E\



1) MATERIAL: MANUFACTURED FROM D6006-129

FINISHED LENGTH = 124.362±0.020

2) FINISH: a) CHEMICAL CONVERSION COAT PER DART QSI 005 4.1

b) PRIME INSIDE AND OUTSIDE PER DART QSI 005 4.2

c) MASK UNDERSIDE OF CROSSTUBE AS SHOWN (ZN C6-2 / C6-3, HATCHED AREA)

d) PAINT OUTSIDE PER DART QSI 005 4.2

e) REMOVE MASKING AND APPLY MATTE CLEAR COAT

3) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED.

UNITS: INCHES UNLESS OTHERWISE NOTED.

BREAK SHARP EDGES: 0.005 TO 0.010 MAX.

- IDENTIFICATION: SCRIBE DART PART NUMBER "D212-664-XXX" AND BATCH NUMBER ON INSIDE OF CUFF USING VIBRATING STYLUS.
- 7) WEIGHT: D212-664-241/-241B = 44.2 lbs
- PART IS SYMMETRIC ABOUT CENTERLINE.
- EXTREME CARE MUST BE TAKEN TO PROTECT THE OUTSIDE SURFACE OF THE TUBE. THE OUTSIDE SURFACE MUST BE SMOOTH AND FREE FROM SURFACE DEFECTS SUCH AS SCRATCHES, NICKS, OR DENTS. DEFECTS UP TO 0.005" MAY BE BLENDED OUT LONGITUDINALLY. CIRCUMFERENTIAL GRIND MARKS ARE UNACCEPTABLE.

10) RUN CUTTER OFF PART. BLEND OUT EDGE LONGITUDINALY, TRANSITION SHOULD BE SMOOTH.

BENDING

11) BEND PROGRESSIVELY WITH A MINIMUM OF 5 PASSES. MAXIMUM TUBE FLATTENING DUE TO BENDING IS 7.2% (BASED ON O.D.) IN LOWER HALF OF R35.5 BEND AND 6% (BASED ON O.D.) ON REMAINING TUBE.

12) LIQUID PENETRÁNT INSPECT OUTSIDE SURFACE OF CROSSTUBE PER QSÍ 038.

ASSEMBLY



13) INSTALL D2940-1 / D5018-1 SUPPORT: ABRADE MATING SURFACE OF SUPPORT AND CROSSTUBE WITH 180-GRIT SANDPAPER AND REMOVE RESIDUE WITH MEK (OR EQUIVALENT). APPLY A 0.04" TO 0.07" THICK LAYER OF PROSEAL 890 CLASS B-2 (OR AMS-S-8802 CLASS B-2) SEALANT TO MATING SURFACE OF SUPPORT.



14) INSTALL MS21920-28 CLAMPS (OR -30) WITH D3595-063-530 RUBBER CUSHIONS TO SECURE THE SUPPORT ON TOP SIDE OF THE CROSSTUBE. ENSURE CLAMPS ARE ON TOP SIDE OF CROSSTUBE.



15) TORQUE CLAMPS 80 TO 100 IN-LB. ENSURE AT LEAST 1.5 THREADS SHOWING IN SAFETY AND THAT NUT HAS NOT BOTTOMED-OUT AFTER TORQUING. PRIOR TO PACKAGING, RE-CHECK TORQUE ON CLAMPS AFTER PROSEAL 890 **SEALANT HAS CURED FOR 72 HOURS.**



DATE 14.04.01			CROSSTUBE ASS'Y (205/212 HI AFT) NTS COPYRIGHT © 2000 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT			
APPROVED		1	TITLE		SCALE	
MFG. APPR.		Jest !	D212-664-241 SHEET 1 OF 5			
CHECKED		DW.	DRAWING NO.		REV. E	
DRAWN		P	HAWKESBURY, ONTARI] ′
DESIGN		P	DART AEROSPA	ACE	LTD	1
REV.	DESCRIPTION			BY	DATE	1
Α	NEW ISSUE			CP	00.12.12	1
В	ADD HOLES FOR COMPATABILITY WITH BHT/AA SKIDTUBES			PH	05.02.04	
С	REMOVE -1009 ABRASION STRIP; ADD MAGNOBOND 6398, CUSHION, REVERSE CLAMPS			PH	07.03.08	
ם	REFORMAT/REVISE GENERAL NOTES/PART LIST; REORGANIZED VIEWS AND REFORMATTED DRAWING TO CURRENT STANDARDS; ADD -241B (ZN D4-2, B4-2); REMOVED REF & ADD TOLERANCES (ZN D8-3 & C4-3, C6-3 & A8-3); RELOCATED FLAG #6 PER PAR 08-046 (ZN A5-3); MOVED TURNING DETAIL & UPDATED TOLERANCE TO SHEET 4				09.09.30	
ш	D5018-1 WAS D2940-1 (-241B), PROSEAL WAS MAGNOBOND, NOTE 2: ADD INSPECTION WINDOW, NOTE 11: ALLOW 7.2% CRUSH, NOTE 15: ADD 72HR CURE AND RETORQUE FOR PROSEAL, ADD SHEET 3, CLAMPS REVERSED TO PREVENT CHAFING (ZN B7-2, B7-3), BEND HEIGHT TOL. NOW 0.25 WAS 0.13 (C1-4), INCORP DEO D-1/-2				14.04.01	







